

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FU869 **O'DWYER GARDENS (SURFSIDES)**
WSW **2959 WEST 33RD STREET**
> 1 **BROOKLYN, NY 11224**

1.171 mi.
6181 ft.

Site 2 of 4 in cluster FU

NY LTANKS **U000410712**
NY UST **N/A**
NY Spills

Relative:
Higher

Actual:
8 ft.

LTANKS:

Name: O'DWYER HOUSES
Address: 2959 WEST 33RD STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9315460 / 1995-04-26
Facility ID: 9315460
Site ID: 201620
Spill Date: 1991-09-18
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C3
Cleanup Ceased: 1995-04-26
SWIS: 2401
Investigator: HEALY
Referred To: Not reported
Reported to Dept: 1994-03-30
CID: Not reported
Water Affected: Not reported
Spill Notifier: DEC
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1994-04-05
Spill Record Last Update: 1995-04-26
Spiller Name: Not reported
Spiller Company: NYCHA - JOE MONTELLA
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 167749
DEC Memo: ""
Remarks: "LEAK RATE OF 0.07 GPH - REPORTED AS PASSED BY TESTER. SEE SPILL # 9416977"

All TTF:

Facility ID: 9315460
Spill Number: 9315460
Spill Tank Test: 1542565
Site ID: 201620
Tank Number: 001
Tank Size: 0
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:

Site ID: 201620
Operable Unit ID: 993566
Operable Unit: 01
Material ID: 387212
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

Name: O'DWYER HOUSES
Address: 2959 WEST 33RD STREET
City, State, Zip: BROOKLYN, NY
Spill Number/Closed Date: 9315461 / 1995-04-26
Facility ID: 9315461
Site ID: 201621
Spill Date: 1992-03-28
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C3
Cleanup Ceased: 1995-04-26
SWIS: 2401
Investigator: HEALY
Referred To: Not reported
Reported to Dept: 1994-03-30
CID: Not reported
Water Affected: Not reported
Spill Notifier: DEC
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1994-04-05
Spill Record Last Update: 1995-04-26
Spiller Name: Not reported
Spiller Company: NYCHA - JOE MONTELLA
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 167749
DEC Memo: ""
Remarks: "LEAK RATE OF 0.09 GPH - REPORTED AS PASSED BY TESTER. SEE SPILL # 9415851"

All TTF:

Facility ID: 9315461

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Spill Number: 9315461
Spill Tank Test: 1542566
Site ID: 201621
Tank Number: 002
Tank Size: 0
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:

Site ID: 201621
Operable Unit ID: 993567
Operable Unit: 01
Material ID: 387213
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

Name: O'DWYER GARDENS -NYCHA
Address: 2959 WEST 33RD STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9415851 / Not Reported
Facility ID: 9415851
Site ID: 201622
Spill Date: 1995-03-07
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: AAOBLIGA
Referred To: WP SUBMITTED 2/28/12
Reported to Dept: 1995-03-07
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 1
Date Entered In Computer: 1995-03-08
Spill Record Last Update: 2017-06-05
Spiller Name: Not reported
Spiller Company: NYC HOUSING AUTHORITY

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 167749
DEC Memo: "12/20/05: This spill transferred from J.Kolleeny to S.Kraszewski.
09/01/06: DEC Lead for this spill changed from unassigned to S.
Kraszewski. - J. Kolleeny 02/09/07 - J.Kann - Spill reassigned from
S.Kraszewski to J.Kann. 01/15/08- J.Kann - Spill consolidated with
closed spill 9416977. 03/1/12: J.kann - iwp submitted 2/28/12 and
edoced today. 10/14/15: J.Kann- site included in the NYCHA Sandy
recovery list and is slated for UST removal. Brief summary provided
to Thomas Larison 518-785-2361 of CBI today in an email. 4/27/16:
J.Kann - the following email was sent to NYCHA on 1/17/16: Yelena- I
am reviewing the investigative work plan (Plan) for O'Dwyer Houses
prepared by Gannett Fleming. Based on review of my files and the
Plan, there seems to be a discrepancy. The Plan includes an
investigation around spill 9011619 (2950 West 33rd? or 35th) and not
spill 9415851 (2959 West 33rd Street). Spill 9011619 for O'Dwyer
Houses and the 15,000 gallon UST was already investigated and closed.
Spill 9415851 still needs to be investigated (the area around (2)
removed 30,000 gallon tanks). It appears they were replaced with a
20,000 gallon UST in 2000. The investigation around these USTs is not
included in the Plan. The Plan will need to be revised to investigate
the area around the former 30,000 gallon USTs. If you have any
additional knowledge about the site that could help clarify this,
please call to discuss. We may need to do a site visit to confirm the
area to be investigated. Thanks -Jennifer 06/05/2017: J.Kann - Spill
reassigned to Andre Obligado."
Remarks: "COULD NOT MAINTAIN LEVEL-TANK #2"

All TTF:

Facility ID: 9415851
Spill Number: 9415851
Spill Tank Test: 1543650
Site ID: 201622
Tank Number: 002
Tank Size: 0
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:

Site ID: 201622
Operable Unit ID: 1009299
Operable Unit: 01
Material ID: 371029
Material Code: 0001A
Material Name: #2 fuel oil

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: O'DWYER GARDENS -NYCHA
Address: 2959 WEST 33RD STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9416977 / 2008-01-15
Facility ID: 9416977
Site ID: 322203
Spill Date: 1995-03-31
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: jkkann
Referred To: CONSOLIDATED WITH 9415851
Reported to Dept: 1995-03-31
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1995-03-31
Spill Record Last Update: 2008-01-15
Spiller Name: Not reported
Spiller Company: NYC HOUSING AUTHORITY
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 167749
DEC Memo: "12/20/05: This spill transferred from J.Kolleeny to S.Kraszewski.
09/01/06: DEC Lead for this spill changed from unassigned to S.
Kraszewski. - J. Kolleeny 02/09/07 - J.Kann - Spill reassigned from
S.Kraszewski to J.Kann. 01/15/08- J.Kann - Spill closed and
consolidated with 9415851."
Remarks: "COULD NOT MAINTAIN LEVEL"

All TTF:

Facility ID: 9416977
Spill Number: 9416977
Spill Tank Test: 1543711
Site ID: 322203
Tank Number: 001
Tank Size: 0
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:

Site ID: 322203
Operable Unit ID: 1014085
Operable Unit: 01
Material ID: 368601
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: O'DWYER GARDENS -NYCHA
Address: 2959 WEST 33RD STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9107041 / 1995-04-26
Facility ID: 9107041
Site ID: 148893
Spill Date: 1991-10-01
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C3
Cleanup Ceased: 1995-04-26
SWIS: 2401
Investigator: HEALY
Referred To: Not reported
Reported to Dept: 1991-10-01
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1991-10-04
Spill Record Last Update: 2005-12-20
Spiller Name: MR CARTER
Spiller Company: NYCHA
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 167749
DEC Memo: ""
Remarks: "REPAIR & RETEST. SEE SPILL # 9415851"

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

All TTF:

Facility ID: 9107041
Spill Number: 9107041
Spill Tank Test: 1539117
Site ID: 148893
Tank Number: Not reported
Tank Size: 0
Material: 0008
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:

Site ID: 148893
Operable Unit ID: 961283
Operable Unit: 01
Material ID: 419274
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: G
Recovered: .00
Oxygenate: Not reported

UST:

Name: O'DWYER GARDENS (SURFSIDES)
Address: 2959 WEST 33RD STREET
City,State,Zip: BROOKLYN, NY 11224
Id/Status: 2-473979 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 584695.12917
UTM Y: 4491882.07477
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 20869
Affiliation Type: Facility Owner
Company Name: NYC HOUSING AUTHORITY
Contact Type: SUPERVISOR
Contact Name: YELENA TKACH
Address1: 23-02 49TH AVENUE
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Phone: (718) 707-5725
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2018-10-23

Site Id: 20869
Affiliation Type: Mail Contact
Company Name: NYC HOUSING AUTHORITY
Contact Type: Not reported
Contact Name: YELENA TKACH
Address1: 23-02 49TH AVENUE
Address2: 5TH FLOOR
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 707-5725
EMail: YELENA.TKACH@NYCHA.NYC.GOV
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2018-10-11

Site Id: 20869
Affiliation Type: Facility Operator
Company Name: ODWYER GARDENS (SURFSIDES)
Contact Type: Not reported
Contact Name: NYC HOUSING AUTHORITY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 707-5725
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2018-10-11

Site Id: 20869
Affiliation Type: Emergency Contact
Company Name: NYC HOUSING AUTHORITY
Contact Type: Not reported
Contact Name: EMERGENCY SERVICE DEPT.
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 707-5900
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2013-01-31

Tank Info:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Tank Number: 1
Tank ID: 59518
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 20000
Install Date: 02/01/2000
Date Tank Closed: 09/17/2018
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: E
Modified By: DAFRANCI
Last Modified: 10/11/2018

Equipment Records:

B04 - Tank External Protection - Fiberglass
I02 - Overfill - High Level Alarm
L09 - Piping Leak Detection - Exempt Suction Piping
E04 - Piping Secondary Containment - Double walled UG
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
K00 - Spill Prevention - None
F05 - Pipe External Protection - Jacketed
H05 - Tank Leak Detection - In-Tank System (ATG)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser

Tank Number: OLD 1
Tank ID: 37578
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 30000
Install Date: 02/01/1969
Date Tank Closed: 02/01/2000
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: OLD 2
Tank ID: 37579
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 30000
Install Date: 02/01/1969
Date Tank Closed: 02/01/2000
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

SPILLS:

Name: O'DWYER GARDENS -NYCHA
Address: 2959 WEST 33RD STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0305816 / 2007-01-26
Facility ID: 0305816
Facility Type: ER
DER Facility ID: 167749
Site ID: 322201
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2003-09-02
Investigator: jkkann
Referred To: CLOSED PER NYCHA INFO
Reported to Dept: 2003-09-02
CID: 199

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2003-09-02
Spill Record Last Update: 2007-01-26
Spiller Name: Not reported
Spiller Company: EASTCO BOILER
Spiller Address: 1175 LEGETT AVE
Spiller Company: 001
Contact Name: FRANK INOA
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

KOLLEENY Eastco Boiler - Same company as A.L. Eastmond Contact: AL Eastmond - Fergusen 347-865-7456 Housing Authority - Frank Inoa 718-707-5718 A small copper tube in a mobile boiler broke. Oil leaked out of the boiler and into the truck bed, out onto the sidewalk/street and some went into a DEP storm drain. Eastmond is on site cleaning the area. They will also open and clean the storm drain. 11/03/05: This spill transferred from J.Kolleeny to S.Kraszewski. 01/27/06: This spill transferred from S.Kraszewski to Q.Abidi. 03/31/06: This spill transferred from Q. Abidi to Koon Tang. 1/26/07 - Spill transferred to J. Kann. Spill closed as per information on clean up provided by NYCHA. - J.Kann "
Remarks: "broken line on boiler caused spill - material contained to concrete floor and boiler area "

All Materials:

Site ID: 322201
Operable Unit ID: 874260
Operable Unit: 01
Material ID: 503054
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 80.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: O'DWYER GARDENS -NYCHA
Address: 2959 WEST 33RD STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0305818 / 2003-09-02
Facility ID: 0305818
Facility Type: ER
DER Facility ID: 167749
Site ID: 322202
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2003-09-02
Investigator: MXTIPPLE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Referred To:	Not reported
Reported to Dept:	2003-09-02
CID:	216
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-09-02
Spill Record Last Update:	2005-12-20
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller Company:	999
Contact Name:	MALORY GILMORE
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE no call back number, no way to confirm"
Remarks:	"SPILL IN A PORTABLE BOILER NOTHING FURTHER DEP HAD NO OTHER INFO "
All Materials:	
Site ID:	322202
Operable Unit ID:	872413
Operable Unit:	01
Material ID:	503055
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	80.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported